

00542801.082100




Figure 1

09642301.082100




Figure 2

001280" 10824950




Figure 3





Figure 4




Frame Structure


KNOWN ART

Figure 5

001280" 10824960



Node Record Figure 6



Node Link Figure 9






Figure 9A



Path Link Figure 8



Device Record

Figure 7

09642801.082100




Figure 10




Figure 11

New initiator login




Figure 12

09642801.082100




Figure 13

REPAIR
Detected

Zero probation
time

Mark ~~mark~~
Probationary

14100

1402



Figure 14

09642801.082100

00674201-0000




Figure 15